National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 04/06/2001

F	Γ	۷	۷	0	0	F	Α	0	8	3	E
---	---	---	---	---	---	---	---	---	---	---	---

File No. 312	02/16/2000	MCALESTER, OK	Aircraft Reg No.	N9505B	Time (Local): 07:48 CST		
Engine Make/Mode Aircraft Damag Number of Engine Operating Certificate(s Name of Carrie	s: 1): On-demand Air Taxi r: MARTINAIRE INC. n: Non-scheduled; Domesti	c; Cargo muter	Crew Pass	Fatal 0 0	Serious 0 0	Minor/None 1 0	
Last Depart. Poir Destination	t: Same as Accident/Incide			Weath Basi Low Wind Tempe Obst	c Weather: \ est Ceiling: 6 Visibility:	Weather Observation Facility Visual Conditions 6500 Ft. AGL, Overcast 10.00 SM 020 / 016 Kts 9 None	
Pilot-in-Command Ag Certificate(s)/Rating(s) Airline Transport; Multi-engine La Instrument Ratings Airplane	e: 33 and; Single-engine Land		Т	Total Las Total M	me (Hours) All Aircraft: 4 st 90 Days: 3 ake/Model: 9 ment Time: 2	333 971	

See brief narrative for FTW00FA083A.

Brief of Accident (Continued)

FTW00FA083B

File No. 312 02/16/2000 MCALESTER, OK Aircraft Reg No. N9505B Time (Local): 07:48 CST

Occurrence #1: MIDAIR COLLISION Phase of Operation: MANEUVERING

Findings

1. (C) VISUAL LOOKOUT - NOT MAINTAINED - PILOT IN COMMAND

2. (C) VISUAL LOOKOUT - NOT MAINTAINED - PILOT OF OTHER AIRCRAFT

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows. The failure of both pilots to maintain visual lookout while maneuvering in the traffic pattern.